

Ferrer's Avenue Playing Field Working Party Report, Field Boundary Repair Excerpt

(Russell Lock, Lesley Evans, Chrys Smedley, Mary Upton)

Field Boundary Repair

1. We suggest removal of the existing earth bridge, seen below in Figures 1 & 2 to discourage exit from Ferrers playing fields onto the busy main road.



Figure 1 Earth Bridge over ditch



Figure 2 Approach from Ferrer's to Redhill Lane

2. Re-introduction of traditional hawthorn hedging in the uncovered areas. We believe this would be the most environmentally suitable solution as it discourages passage, provides a habitat for local wildlife, and would be more long lasting than a traditional fence.
3. Protection of new hedging temporarily with the use of chestnut fencing, see figure 3.



Figure 3 Chestnut Fencing example